03500.015259. (35.C15259)



PATENT



IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

In re Patent of:	.)
	: Examiner: F. L. Evans
TOMOHIRO SUZUKI, et al.)
	: Group Art Unit: 2877
Application No.: 09/764,049)
	Certificate
Filed: January 19, 2001) — Cale
	AUG 0.9 2006 of Correction
For: FLUOROMETRY AND	
FLUOROMETRIC DEVICE	: Of Correction
AND SUBSTRATE)
SUITABLE THEREFOR	:
)
U.S. Patent No.: 6,963,397	:
) .
Issued: November 8, 2005	: August 3, 2006

Commissioner for Patents P.O. Box 1450 Alexandria, VA 22313-1450

REQUEST FOR CERTIFICATE OF CORRECTION UNDER RULES 322 AND 323

Sir:

It is respectfully requested that a Certificate of Correction be issued by the Patent and Trademark Office due to errors which appear in the printed patent as a result of Patent and Trademark Office mistakes, and mistakes of a clerical, typographical of 506,037/2006 SDENBORI 506,03397 minor character, which were not the fault of the Patent and Trademark Office. A 169.69 OP Certificate of Correction form, in duplicate, is enclosed.

Accompanying this letter is a check for \$100.00 to cover the statutory fee for such Certificate of Correction.

AUG -9 LUUD

Patentees' undersigned attorney may be reached in our Costa Mesa, California office by telephone at (714) 540-8700. All correspondence should continue to be directed to our address given below.

Respectfully submitted,

Damond E. Vadnais
Attorney for Patentees

Registration No.: 52,310

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza
New York, New York 10112-3800
Facsimile: (212) 218-2200

CA_MAIN 117953v1

CERTIFICATE OF CORRECTION

PATENT NO. : 6,963,397

DATED

: November 8, 2005

INVENTOR(S) :

TOMOHIRO SUZUKI, et al.

Page 1 of 2

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 4

Line 9, "thereby" should read --whereby--;

Line 66, "illumination portions" should read --illumination portion--; and

Line 67, "detecting portions" should read --detecting portion--.

COLUMN 5

Line 2, "one-different spots" should read -- one different spot--;

Line 5, "spots" should read --spot--;

Line 32, "types" should read --type--;

Line 41, "probes" should read --probe--; and

Line 56, "left" should read --left to--.

COLUMN 6

Line 56, "a Measurements" should read -- Measurements--.

COLUMN 7

Line 11, "left" should read --left to--; and

Line 37, "of the substrate was" should read -- of the substrate were--.

COLUMN 8

Line 48, "a terminal" should read --terminal--; and

Line 65, "the-circumference" should read -- the circumference--.

COLUMN 9

Line 53, "probes are" should read --probe is--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO

30 Rockefeller Plaza

New York, New York 10112-3800

(212) 218-2100 - Telephone

(212) 218-2200 - Facsimile

Form PTO 1050 (Rev. 3-82)

117946 (Form#30)

PATENT NO. <u>6,963,397</u>

No. of add'l. copies @ 30¢ per page

AUG -9: LYUB

CERTIFICATE OF CORRECTION

PATENT NO. :

6,963,397

DATED

November 8, 2005

INVENTOR(S) :

TOMOHIRO SUZUKI, et al.

Page 2 of 2

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 10

Line 8, "D Sequence" should read -- Sequence--; and

Lines 34-42, "ACTGGCCGCT TTTTTACA 18

SEQ. ID No.: 4

Length: 18

Type: Nucleic Acid

Strandedness: Single Strand

Topology: Linear

Molecule type: Other Nucleic Acid, Synthetic DNA

Sequence

ACTGGCATCT TGTTTACA 18" should be deleted.

COLUMN 12

Line 2, "is performed" should read -- are performed--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza New York, New York 10112-3800

(212) 218-2200 - Facsimile

Form PTO 1050 (Rev. 3-82) 117946 (Form#30)

(212) 218-2100 - Telephone

PATENT NO. <u>6,963,397</u>

No. of add'l. copies @ 30¢ per page

03500.015259. (35.C15259)



PATENT

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

HI IC I	ratent or.	. <i>)</i>	
		:	Examiner: F. L. Evans
TOM	OHIRO SUZUKI, et al.)	
A 1!		:	Group Art Unit: 2877
Appli	cation No.: 09/764,049)	
Filed:	Innuary 10, 2001	:	
riicu.	January 19, 2001)	
For:	FLUOROMETRY AND	`	
2 01,	FLUOROMETRIC DEVICE	,	
	AND SUBSTRATE	·)	
	SUITABLE THEREFOR	:	
)	
U.S. F	Patent No.: 6,963,397	:	
)	
Issued	l: November 8, 2005	:	August 3, 2006

Commissioner for Patents P.O. Box 1450 Alexandria, VA 22313-1450

REQUEST FOR CERTIFICATE OF CORRECTION UNDER RULES 322 AND 323

Sir:

It is respectfully requested that a Certificate of Correction be issued by the Patent and Trademark Office due to errors which appear in the printed patent as a result of Patent and Trademark Office mistakes, and mistakes of a clerical, typographical, or minor character, which were not the fault of the Patent and Trademark Office. A Certificate of Correction form, in duplicate, is enclosed.

Accompanying this letter is a check for \$100.00 to cover the statutory fee for such Certificate of Correction.

Patentees' undersigned attorney may be reached in our Costa Mesa, California office by telephone at (714) 540-8700. All correspondence should continue to be directed to our address given below.

Respectfully submitted,

Damond E. Vadnais
Attorney for Patentees
Registration No.: 52,310

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza
New York, New York 10112-3800
Facsimile: (212) 218-2200

CA_MAIN 117953v1

CERTIFICATE OF CORRECTION

PATENT NO.

6,963,397

DATED

November 8, 2005

INVENTOR(S) :

TOMOHIRO SUZUKI, et al.

Page 1 of 2

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 4

Line 9, "thereby" should read --whereby--;

Line 66, "illumination portions" should read --illumination portion--; and

Line 67, "detecting portions" should read --detecting portion--.

COLUMN 5

Line 2, "one-different spots" should read -- one different spot--;

Line 5, "spots" should read --spot--;

Line 32, "types" should read --type--;

Line 41, "probes" should read --probe--; and

Line 56, "left" should read --left to--.

COLUMN 6

Line 56, "a Measurements" should read -- Measurements--.

COLUMN 7

Line 11, "left" should read --left to--; and

Line 37, "of the substrate was" should read -- of the substrate were--.

COLUMN 8

Line 48, "a terminal" should read --terminal--; and

Line 65, "the-circumference" should read -- the circumference--.

COLUMN 9

Line 53, "probes are" should read --probe is--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO

30 Rockefeller Plaza

New York, New York 10112-3800

(212) 218-2100 - Telephone

(212) 218-2200 - Facsimile

Form PTO 1050 (Rev. 3-82) 117946 (Form#30)

PATENT NO. <u>6,963,397</u>

No. of add'l. copies @ 30¢ per page

CERTIFICATE OF CORRECTION

PATENT NO.

6,963,397

DATED

November 8, 2005

INVENTOR(S) :

TOMOHIRO SUZUKI, et al.

Page 2 of 2

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 10

Line 8, "D Sequence" should read -- Sequence--; and

Lines 34-42, "ACTGGCCGCT TTTTTACA 18

SEQ. ID No.: 4

Length: 18

Type: Nucleic Acid

Strandedness: Single Strand

Topology: Linear

Molecule type: Other Nucleic Acid, Synthetic DNA

Sequence

ACTGGCATCT TGTTTACA 18" should be deleted.

COLUMN 12

Line 2, "is performed" should read -- are performed--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza New York, New York 10112-3800 (212) 218-2100 - Telephone

(212) 218-2100 - Telepholic (212) 218-2200 - Facsimile

Form PTO 1050 (Rev. 3-82) 117946 (Form#30)

PATENT NO. <u>6,963,397</u>

No. of add'l. copies @ 30¢ per page

